

Production Attainment

Benchmarks, Definition & Measurement Details

**SAMPLE
CONTENT & DATA**



Production Attainment

Definition & Measurement Details



What is Production Attainment?

The number of units manufactured by the company (on an assembly line, the manufacturing floor, etc.) divided by target production output over a certain period of time, as a percentage.

Why should this KPI be measured?

Production Attainment measures the degree to which the Manufacturing function is capable of reaching its targeted production output. A manufacturing plant's attainment rate can be negatively impacted by

How is this KPI calculated?

Two values are used to calculate this KPI: (1) the actual output that the Manufacturing function produces (in units) and (2) the targeted output that the Manufacturing function is expected to produce (in units) during the

ABRIDGED CONTENT
Purchase to View Full Definition & Measurement Details!

Production Attainment

Benchmarks & Characteristics of High Performers



Production Attainment

(Actual Production Output in Units / Target Production Output in Units) * 100



Characteristics of High Performers

- KPIs are well-defined, tracked and tied to performance reviews
- Robust self-service options for customer

Sample Size: XX

KPI Type: XX

Unit: XX

Is High or Low Best?: XX

How to read this chart: This chart summarizes the performance gaps between high (Top 5%), mid (Median) and low (Bottom 5%) performers for this Key Performance Indicator (KPI). For example, the column labeled "Top 5%" represents a company that outperformed 95% of the peer group observed for this metric.

Benchmarking Report Terms & Conditions

OpsDog KPI Reports



© 2017 OpsDog, Inc.

The OpsDog KPI Reports and their contents are protected by copyright laws, contain the trademark OpsDog, Inc., and are OpsDog's proprietary information. No part of this book shall be reproduced, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording or otherwise, without written permission from OpsDog, Inc.

OpsDog, Inc. assumes no liability with respect to the use of the information contained herein which is provided "as is" and there are no warranties of any kind provided by OpsDog with respect to this report. OpsDog assumes no responsibility for errors or omissions and will not be liable for any damages resulting from the use of the information contained herein.

OpsDog, Inc.

1502 Augusta Dr., Suite 200

Houston, TX 77057

Tel: 844-650-2888